

## VP1 AND VP3 GREEN MACHINE

ITEM	OLD NO.	NEW NO.	DESCRIPTION
1	30011	653628	VP1 OUTER LID-STAINLESS
	30006	653627	VP3 OUTER LID-POLY (GREEN)
2	30-0018	0US127	BUSHING
3	30-0016	0US233	"T" HANDLE
4	30010	653626	INNER BUCKET & LID
5	30-0014	0US005	OCTAGON DRIVE CASTING
6	N/A	N/A	MAIN BODY
7	1022	0US196	ELECTRICAL CORD
8	30-0052	0US136	VP3 BASE - GREEN
	30-0042	0US134	VP1 BASE - GRAY
9	30-007	0US166	TIMER KNOB ONLY
10	30-0004	0US171	TIMER WITH KNOB
11	1157	0US031	6-32" X 1/2" SCREW
12	1520	0US251	STRAIN RELIEF
13	30-0047	0US104	1/2" X 8" SHEET METAL SCREW
14	30-0046	0US135	COVER PLATE
15	30-0013	0US247	CAPACITOR ON MOTOR
	30-0006	0US016	CAPACITOR (OLD STYLE)
16	30-0015	0US014	MOUNTING STRAP (OLD STYLE)
17	30004	0US250	MOTOR - FRANKLIN W/CAP
18	22-0028	0US331	GROMMET
19	30-0034	0US188	CASTER - FLAT
20	30-0039	0US072	1/4" FLAT WASHER (LRG)
21	30-0038	0US074	1/4" LOCK WASHER
22	30-0037	0US070	1/4" - 20 X 3/4" BOLT
23	30-5001	0US068	1/4" - 20 X 1" BOLT
24	30-5003	0US073	1/4" FLAT WASHER (SM)


### NOT SHOWN

30-0036 0US243 VPI LID HOOK

## WIRING DIAGRAM

Machine shall be connected to the branch circuit with overcurrent protection of 15 Amps.

Franklin motor w/seperate capacitor.



Franklin and Von Weise motor w/capacitor attached.

